



CAUTION: PROTECT BALLS AND RACES FROM SAWDUST, DIRT, PAINT, ETC. SHOULD BEARING BECOME "ROUGH" FROM DIRTY RACES, FLUSH THOROUGHLY WITH HOT SOAPY WATER, RINSE, OVEN DRY AND RE-OIL.



THERE MAY BE 2 TO 4 BALLS LEFT OUT DUE TO MANUFACTURING PROCESS.

PART STAMPED WITH TRIANGLE NAME STAMP

3	BALLS12	BALL	1
2	1866	PLAIN RACE	1
1	1865	LOCKING RACE	1
DET	PART NUMBER	DESCRIPTION	AMT
C TRIANGLE MANUFACTURING CO. OSHKOSH, WI.			
NAME 12" LAZY SUSAN BRG. ASS'Y			
FIT		USED IN	
ELECTRO GALV		LML	
MATERIAL		DRAWN	
SEE DETAIL		LML	
ALL DIMS. 1.020 UNLESS OTHERWISE SPECIFIED		CHECKED	
		SP	
SCALE		1 / 1	

12C

CHANGE LEVEL
P 07-31-06